

Oil Field Environmental Incident Summary

Incident: 20141022120415

Date/Time of Notice: 10/22/2014 12:04

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: HAYMAKER 31-15MBH-A

Field Name: ELIDAH

Well File #: 27699

Date Incident: 10/21/2014

Time Incident: 08:47

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 97

Sec: 15

Qtr:

Location Description:

Submitted By: Josh Gandy

Received By:

Contact Person: Josh Gandy

PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1.5	Barrels	1.5	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

12ft by 8ft

Potential Environmental Impacts:

None

Action Taken or Planned:

Well was shut in and line was replaced within one hour and well was opened back up without incident.

Wastes Disposal Location: This soil will be hauled to an approved disposal site. Indian Hills

Agencies Involved:

Updates

Date: 10/27/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.